

adpmap-5f-8S0-035-049_MIB2
;SW:8S0-035-049 HW:8S0-035-049 --- Information Electr.
;Component:MU-H-LN-CN 040 0343,
Coding:027300030000000011110002000808101F0203A401200100FE
;EV_MUHig6C3Gen2AW7,001260,EV_MUHig6C3Gen2AW7_BY63.rod
;Thursday,05,November,2015,16:25:45:40275
;VCDS Version: Release 15.7.1 (x64) Data version: 20150904
;VCID: 70EA55E5AB3E40BEAD-8024

(1)-Activating and deactivating all development
messages-Infotainment_CAN_Messages,OFF
(2)-Activating and deactivating all development messages-MIB_CAN_Messages,OFF
(1)-Audio Management Input Gain Generation 2-TV Tuner,-128
(2)-Audio Management Input Gain Generation 2-Radio (FM),-128
(3)-Audio Management Input Gain Generation 2-Radio (AM),-128
(4)-Audio Management Input Gain Generation 2-Digital radio (DAB),-128
(5)-Audio Management Input Gain Generation 2-Satellite radio,-128
(6)-Audio Management Input Gain Generation 2-Tuner_TI,-128
(7)-Audio Management Input Gain Generation 2-Media_AUXIN,-128
(8)-Audio Management Input Gain Generation 2-Media_AUX_Adapter,-128
(9)-Audio Management Input Gain Generation 2-Media_CDA,-128
(10)-Audio Management Input Gain Generation 2-Media_DVD,-128
(11)-Audio Management Input Gain Generation 2-Media_MFP,-128
(12)-Audio Management Input Gain Generation 2-Media_BTDevice,-128
(13)-Audio Management Input Gain Generation 2-TA_Tuner_FM,-128
(14)-Audio Management Input Gain Generation 2-Media_Bluray,-128
(15)-Audio Management Input Gain Generation 2-Media_HDMI,-128
(16)-Audio Management Input Gain Generation 2-Tuner_Online,-128
(17)-Audio Management Input Gain Generation 2-Media_Airplay,-128
(18)-Audio Management Input Gain Generation 2-Media_UPNP,-128
(19)-Audio Management Input Gain Generation 2-Media_Cloud,-128
(20)-Audio Management Input Gain Generation 2-Tuner_Personal,-128
(21)-Audio Management Input Gain Generation 2-Tone_Beep,-128
(22)-Audio Management Input Gain Generation 2-Tone_Warning,-128
(23)-Audio Management Input Gain Generation 2-Tone_Touchscreen,-128
(24)-Audio Management Input Gain Generation 2-Tone_Messaging,-128
(25)-Audio Management Input Gain Generation 2-Exbox_DMB,-128
(26)-Audio Management Input Gain Generation 2-Mirrorlink,-128
(27)-Audio Management Input Gain Generation 2-TTS_Nav,-128
(28)-Audio Management Input Gain Generation 2-TTS_SDS,-128
(29)-Audio Management Input Gain Generation 2-Phone_Voice,-128
(30)-Audio Management Input Gain Generation 2-Phone_Ringer_MFP,-128
(31)-Audio Management Input Gain Generation 2-Phone_Ringer_OB,-128
(32)-Audio Management Input Gain Generation 2-HFP,0
(33)-Audio Management Input Gain Generation 2-TV_AV_IN,0
Audio management mute function,Muting of audio sources
Automatic ring break diagnostic,No automatic start
Awakening ability on optical databus,OFF
Base volume of speech output,50 %
Bluetooth,On
Bluetooth Audio Codec,FF
Bluetooth: Preferred connection profile for phone book data,PBAP
Bluetooth: Sniff mode,OFF

adpmap-5f-8S0-035-049_MIB2

Brand-specific display of connect application,00.0000 RÁ00\$0;0ö°00°00%

¾ÿ0°Žÿ0°0000070÷0°0>000pá0I00I

6Ê

CD eject button,Enabled

(1)-Check tone frequency-High note frequency range,4000 Hz

(2)-Check tone frequency-Medium note frequency range,1000 Hz

(3)-Check tone frequency-Low note frequency range,100 Hz

Confirmation of installation change,46 1C

(1)-Copy multimedia data-Data medium,On

(2)-Copy multimedia data-Optical drive,On

Country code for mobile network,0

Country identification; country of sale,--

Country identification; country of sale HMI,--

Deactivate production mode,0

Developer mode,activated

(1)-Electrical test of loudspeakers-Mode,automatic

(2)-Electrical test of

loudspeakers-Parameter_AC-Diagnostics_Channel_1_Test_Frequency,19000 Hz

(3)-Electrical test of

loudspeakers-Parameter_AC-Diagnostics_Channel_1_Test_Volume,22

(4)-Electrical test of

loudspeakers-Parameter_AC-Diagnostics_Channel_2_Test_Frequency,19000 Hz

(5)-Electrical test of

loudspeakers-Parameter_AC-Diagnostics_Channel_2_Test_Volume,22

(6)-Electrical test of

loudspeakers-Parameter_AC-Diagnostics_Channel_3_Test_Frequency,19000 Hz

(7)-Electrical test of loudspeaker;SW:8S0-035-049 HW:8S0-035-049 ---

Information Electr.

;Component:MU-H-LN-CN 040 0343,

Coding:027300030000000011110002000808101F0203A401200100FE

;EV_MUHig6C3Gen2AW7,001260,EV_MUHig6C3Gen2AW7_BY63.rod

;Thursday,05,November,2015,16:27:47:40275

;VCDS Version: Release 15.7.1 (x64) Data version: 20150904

;VCID: 70EA55E5AB3E40BEAD-8024

(1)-Activating and deactivating all development

messages-Infotainment_CAN_Messages,OFF

(2)-Activating and deactivating all development messages-MIB_CAN_Messages,OFF

(1)-Audio Management Input Gain Generation 2-TV Tuner,-128

(2)-Audio Management Input Gain Generation 2-Radio (FM),-128

(3)-Audio Management Input Gain Generation 2-Radio (AM),-128

(4)-Audio Management Input Gain Generation 2-Digital radio (DAB),-128

(5)-Audio Management Input Gain Generation 2-Satellite radio,-128

(6)-Audio Management Input Gain Generation 2-Tuner_TI,-128

(7)-Audio Management Input Gain Generation 2-Media_AUXIN,-128

(8)-Audio Management Input Gain Generation 2-Media_AUX_Adapter,-128

(9)-Audio Management Input Gain Generation 2-Media_CDA,-128

(10)-Audio Management Input Gain Generation 2-Media_DVD,-128

(11)-Audio Management Input Gain Generation 2-Media_MFP,-128

(12)-Audio Management Input Gain Generation 2-Media_BTDevice,-128

(13)-Audio Management Input Gain Generation 2-TA_Tuner_FM,-128

(14)-Audio Management Input Gain Generation 2-Media_Bluray,-128

(15)-Audio Management Input Gain Generation 2-Media_HDMI,-128

adpmap-5f-8S0-035-049_MIB2

(16)-Audio Management Input Gain Generation 2-Tuner_Online,-128
 (17)-Audio Management Input Gain Generation 2-Media_Airplay,-128
 (18)-Audio Management Input Gain Generation 2-Media_UPNP,-128
 (19)-Audio Management Input Gain Generation 2-Media_Cloud,-128
 (20)-Audio Management Input Gain Generation 2-Tuner_Personal,-128
 (21)-Audio Management Input Gain Generation 2-Tone_Beep,-128
 (22)-Audio Management Input Gain Generation 2-Tone_Warning,-128
 (23)-Audio Management Input Gain Generation 2-Tone_Touchscreen,-128
 (24)-Audio Management Input Gain Generation 2-Tone_Messaging,-128
 (25)-Audio Management Input Gain Generation 2-Exbox_DMB,-128
 (26)-Audio Management Input Gain Generation 2-Mirrorlink,-128
 (27)-Audio Management Input Gain Generation 2-TTS_Nav,-128
 (28)-Audio Management Input Gain Generation 2-TTS_SDS,-128
 (29)-Audio Management Input Gain Generation 2-Phone_Voice,-128
 (30)-Audio Management Input Gain Generation 2-Phone_Ringer_MFP,-128
 (31)-Audio Management Input Gain Generation 2-Phone_Ringer_OB,-128
 (32)-Audio Management Input Gain Generation 2-HFP,0
 (33)-Audio Management Input Gain Generation 2-TV_AV_IN,0
 Audio management mute function,Muting of audio sources
 Automatic ring break diagnostic,No automatic start
 Awakening ability on optical databus,OFF
 Base volume of speech output,50 %
 Bluetooth,On
 Bluetooth Audio Codec,FF
 Bluetooth: Preferred connection profile for phone book data,PBAP
 Bluetooth: Sniff mode,OFF
 Brand-specific display of connect application,00.000000A000\$0;ü°001000
 Qp°0ap°0000070÷°0>000páI00I 7æ
 CD eject button,Enabled
 (1)-Check tone frequency-High note frequency range,4000 Hz
 (2)-Check tone frequency-Medium note frequency range,1000 Hz
 (3)-Check tone frequency-Low note frequency range,100 Hz
 Confirmation of installation change,46 1C
 (1)-Copy multimedia data-Data medium,On
 (2)-Copy multimedia data-Optical drive,On
 Country code for mobile network,0
 Country identification; country of sale,--
 Country identification; country of sale HMI,--
 Deactivate production mode,0
 Developer mode,activated
 (1)-Electrical test of loudspeakers-Mode,automatic
 (2)-Electrical test of
 loudspeakers-Parameter_AC-Diagnostics_Channel_1_Test_Frequency,19000 Hz
 (3)-Electrical test of
 loudspeakers-Parameter_AC-Diagnostics_Channel_1_Test_Volume,22
 (4)-Electrical test of
 loudspeakers-Parameter_AC-Diagnostics_Channel_2_Test_Frequency,19000 Hz
 (5)-Electrical test of
 loudspeakers-Parameter_AC-Diagnostics_Channel_2_Test_Volume,22
 (6)-Electrical test of
 loudspeakers-Parameter_AC-Diagnostics_Channel_3_Test_Frequency,19000 Hz
 (7)-Electrical test of

loudspeakers-Parameter_AC-Diagnostics_Channel_3_Test_Volume,22
(8)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_4_Test_Frequency,19000 Hz
(9)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_4_Test_Volume,22
(10)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_5_Test_Frequency,19000 Hz
(11)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_5_Test_Volume,22
(12)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_6_Test_Frequency,19000 Hz
(13)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_6_Test_Volume,22
(14)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_7_Test_Frequency,19000 Hz
(15)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_7_Test_Volume,22
(16)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_8_Test_Frequency,19000 Hz
(17)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_8_Test_Volume,22
(18)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_9_Test_Frequency,19000 Hz
(19)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_9_Test_Volume,22
(20)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_10_Test_Frequency,19000 Hz
(21)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_10_Test_Volume,22
(22)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_11_Test_Frequency,0 Hz
(23)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_11_Test_Volume,0
(24)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_12_Test_Frequency,0 Hz
(25)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_12_Test_Volume,0
(26)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_13_Test_Frequency,0 Hz
(27)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_13_Test_Volume,0
(28)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_14_Test_Frequency,0 Hz
(29)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_14_Test_Volume,0
(30)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_15_Test_Frequency,0 Hz
(31)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_15_Test_Volume,22
(32)-Electrical test of
loudspeakers-Parameter_AC-Diagnostics_Channel_16_Test_Frequency,19000 Hz
(33)-Electrical test of

loudspeakers-Parameter_AC-Diagnostics_Channel_16_Test_Volume,22

Fee-based traffic information (TMC),32768

(1)-FM tuner; mono/stereo setting-l_hf_stereo_lower_threshold,37 dBμV

(2)-FM tuner; mono/stereo setting-l_nf_max_stereo_channel_separation,32 dB

(3)-FM tuner; mono/stereo setting-t_hysteresis_mono_to_stereo,15.0 s

Infotainment Recorder,activated

(1)-Installation list; specified installations-ECU coded,Yes

(2)-Installation list; specified installations-ECU coded,No

(3)-Installation list; specified installations-ECU coded,Yes

(4)-Installation list; specified installations-ECU coded,No

(5)-Installation list; specified installations-ECU coded,No

(6)-Installation list; specified installations-ECU coded,No

(7)-Installation list; specified installations-ECU coded,No

(8)-Installation list; specified installations-ECU coded,No

(9)-Installation list; specified installations-ECU coded 2,No

(10)-Installation list; specified installations-ECU coded 2,No

(11)-Installation list; specified installations-ECU coded 2,No

(1)-Interface for external media; activation-Connection 1,activated

(2)-Interface for external media; activation-Connection 2,not activated

(3)-Interface for external media; activation-Connection 3,not activated

(4)-Interface for external media; activation-Connection 4,not activated

Internal SIM card; use,automatic

(1)-Locked menu contents-FB_TUNER_0,non_blocked

(2)-Locked menu contents-FB_TUNER_1,non_blocked

(3)-Locked menu contents-FB_TUNER_2,non_blocked

(4)-Locked menu contents-FB_TUNER_3,non_blocked

(5)-Locked menu contents-FB_TUNER_4,non_blocked

(6)-Locked menu contents-FB_TUNER_5,non_blocked

(7)-Locked menu contents-FB_TUNER_6,non_blocked

(8)-Locked menu contents-FB_TUNER_7,non_blocked

(9)-Locked menu contents-FB_TUNER_8,non_blocked

(10)-Locked menu contents-FB_TUNER_9,non_blocked

(11)-Locked menu contents-FB_TUNER_10,non_blocked

(12)-Locked menu contents-FB_TUNER_11,non_blocked

(13)-Locked menu contents-FB_TUNER_12,non_blocked

(14)-Locked menu contents-FB_TUNER_13,non_blocked

(15)-Locked menu contents-FB_TUNER_14,non_blocked

(16)-Locked menu contents-FB_TUNER_15,non_blocked

(17)-Locked menu contents-FB_MEDIA_0,non_blocked

(18)-Locked menu contents-FB_MEDIA_1,non_blocked

(19)-Locked menu contents-FB_MEDIA_2,non_blocked

(20)-Locked menu contents-FB_MEDIA_3,non_blocked

(21)-Locked menu contents-FB_MEDIA_4,non_blocked

(22)-Locked menu contents-FB_MEDIA_5,non_blocked

(23)-Locked menu contents-FB_MEDIA_6,non_blocked

(24)-Locked menu contents-FB_MEDIA_7,non_blocked

(25)-Locked menu contents-FB_MEDIA_8,non_blocked

(26)-Locked menu contents-FB_MEDIA_9,non_blocked

(27)-Locked menu contents-FB_MEDIA_10,non_blocked

(28)-Locked menu contents-FB_MEDIA_11,non_blocked

(29)-Locked menu contents-FB_MEDIA_12,non_blocked

(30)-Locked menu contents-FB_MEDIA_13,non_blocked

(31)-Locked menu contents-FB_MEDIA_14,non_blocked
(32)-Locked menu contents-FB_MEDIA_15,non_blocked
(33)-Locked menu contents-FB_MEDIA_16,non_blocked
(34)-Locked menu contents-FB_MEDIA_17,non_blocked
(35)-Locked menu contents-FB_MEDIA_18,non_blocked
(36)-Locked menu contents-FB_MEDIA_19,non_blocked
(37)-Locked menu contents-FB_MEDIA_20,non_blocked
(38)-Locked menu contents-FB_MEDIA_21,non_blocked
(39)-Locked menu contents-FB_MEDIA_22,non_blocked
(40)-Locked menu contents-FB_MEDIA_23,non_blocked
(41)-Locked menu contents-FB_PHONE_0,non_blocked
(42)-Locked menu contents-FB_PHONE_1,non_blocked
(43)-Locked menu contents-FB_PHONE_2,non_blocked
(44)-Locked menu contents-FB_PHONE_3,non_blocked
(45)-Locked menu contents-FB_PHONE_4,non_blocked
(46)-Locked menu contents-FB_PHONE_5,non_blocked
(47)-Locked menu contents-FB_PHONE_6,non_blocked
(48)-Locked menu contents-FB_PHONE_7,non_blocked
(49)-Locked menu contents-FB_PHONE_8,non_blocked
(50)-Locked menu contents-FB_PHONE_9,non_blocked
(51)-Locked menu contents-FB_PHONE_10,non_blocked
(52)-Locked menu contents-FB_PHONE_11,non_blocked
(53)-Locked menu contents-FB_PHONE_12,non_blocked
(54)-Locked menu contents-FB_PHONE_13,non_blocked
(55)-Locked menu contents-FB_PHONE_14,non_blocked
(56)-Locked menu contents-FB_PHONE_15,non_blocked
(57)-Locked menu contents-FB_NAV_0,non_blocked
(58)-Locked menu contents-FB_NAV_1,non_blocked
(59)-Locked menu contents-FB_NAV_2,non_blocked
(60)-Locked menu contents-FB_NAV_3,non_blocked
(61)-Locked menu contents-FB_NAV_4,non_blocked
(62)-Locked menu contents-FB_NAV_5,non_blocked
(63)-Locked menu contents-FB_NAV_6,non_blocked
(64)-Locked menu contents-FB_NAV_7,non_blocked
(65)-Locked menu contents-FB_NAV_8,non_blocked
(66)-Locked menu contents-FB_NAV_9,non_blocked
(67)-Locked menu contents-FB_NAV_10,non_blocked
(68)-Locked menu contents-FB_NAV_11,non_blocked
(69)-Locked menu contents-FB_NAV_12,non_blocked
(70)-Locked menu contents-FB_NAV_13,non_blocked
(71)-Locked menu contents-FB_NAV_14,non_blocked
(72)-Locked menu contents-FB_NAV_15,non_blocked
(73)-Locked menu contents-FB_NAV_16,non_blocked
(74)-Locked menu contents-FB_NAV_17,non_blocked
(75)-Locked menu contents-FB_NAV_18,non_blocked
(76)-Locked menu contents-FB_NAV_19,non_blocked
(77)-Locked menu contents-FB_NAV_20,non_blocked
(78)-Locked menu contents-FB_NAV_21,non_blocked
(79)-Locked menu contents-FB_NAV_22,non_blocked
(80)-Locked menu contents-FB_NAV_23,non_blocked
(81)-Locked menu contents-FB_NAV_24,non_blocked
(82)-Locked menu contents-FB_NAV_25,non_blocked

(83)-Locked menu contents-FB_NAV_26,non_blocked
 (84)-Locked menu contents-FB_NAV_27,non_blocked
 (85)-Locked menu contents-FB_NAV_28,non_blocked
 (86)-Locked menu contents-FB_NAV_29,non_blocked
 (87)-Locked menu contents-FB_NAV_30,non_blocked
 (88)-Locked menu contents-FB_NAV_31,non_blocked
 (89)-Locked menu contents-FB_NAV_32,non_blocked
 (90)-Locked menu contents-FB_NAV_33,non_blocked
 (91)-Locked menu contents-FB_NAV_34,non_blocked
 (92)-Locked menu contents-FB_NAV_35,non_blocked
 (93)-Locked menu contents-FB_NAV_36,non_blocked
 (94)-Locked menu contents-FB_NAV_37,non_blocked
 (95)-Locked menu contents-FB_NAV_38,non_blocked
 (96)-Locked menu contents-FB_NAV_39,non_blocked
 (97)-Locked menu contents-FB_CAR_0,non_blocked
 (98)-Locked menu contents-FB_CAR_1,non_blocked
 (99)-Locked menu contents-FB_CAR_2,non_blocked
 (100)-Locked menu contents-FB_CAR_3,non_blocked
 (101)-Locked menu contents-FB_CAR_4,non_blocked
 (102)-Locked menu contents-FB_CAR_5,non_blocked
 (103)-Locked menu contents-FB_CAR_6,non_blocked
 (104)-Locked menu contents-FB_CAR_7,non_blocked
 (105)-Locked menu contents-FB_CAR_8,non_blocked
 (106)-Locked menu contents-FB_CAR_9,non_blocked
 (107)-Locked menu contents-FB_CAR_10,non_blocked
 (108)-Locked menu contents-FB_CAR_11,non_blocked
 (109)-Locked menu contents-FB_CAR_12,non_blocked
 (110)-Locked menu contents-FB_CAR_13,non_blocked
 (111)-Locked menu contents-FB_CAR_14,non_blocked
 (112)-Locked menu contents-FB_CAR_15,non_blocked
 (113)-Locked menu contents-FB_CAR_16,non_blocked
 (114)-Locked menu contents-FB_CAR_17,non_blocked
 (115)-Locked menu contents-FB_CAR_18,non_blocked
 (116)-Locked menu contents-FB_CAR_19,non_blocked
 (117)-Locked menu contents-FB_CAR_20,non_blocked
 (118)-Locked menu contents-FB_CAR_21,non_blocked
 (119)-Locked menu contents-FB_CAR_22,non_blocked
 (120)-Locked menu contents-FB_CAR_23,non_blocked
 (121)-Locked menu contents-FB_MISC_0,non_blocked
 (122)-Locked menu contents-FB_MISC_1,non_blocked
 (123)-Locked menu contents-FB_MISC_2,non_blocked
 (124)-Locked menu contents-FB_MISC_3,non_blocked
 (125)-Locked menu contents-FB_MISC_4,non_blocked
 (126)-Locked menu contents-FB_MISC_5,non_blocked
 (127)-Locked menu contents-FB_MISC_6,non_blocked
 (128)-Locked menu contents-FB_MISC_7,non_blocked
 (129)-Locked menu contents-FB_MISC_8,non_blocked
 (130)-Locked menu contents-FB_MISC_9,non_blocked
 (131)-Locked menu contents-FB_MISC_10,non_blocked
 (132)-Locked menu contents-FB_MISC_11,non_blocked
 (133)-Locked menu contents-FB_MISC_12,non_blocked
 (134)-Locked menu contents-FB_MISC_13,non_blocked

adpmap-5f-8S0-035-049_MIB2

(135)-Locked menu contents-FB_MISC_14,non_blocked
(136)-Locked menu contents-FB_MISC_15,non_blocked
(137)-Locked menu contents-FB_MISC_16,non_blocked
(138)-Locked menu contents-FB_MISC_17,non_blocked
(139)-Locked menu contents-FB_MISC_18,non_blocked
(140)-Locked menu contents-FB_MISC_19,non_blocked
(141)-Locked menu contents-FB_MISC_20,non_blocked
(142)-Locked menu contents-FB_MISC_21,non_blocked
(143)-Locked menu contents-FB_MISC_22,non_blocked
(144)-Locked menu contents-FB_MISC_23,non_blocked
(145)-Locked menu contents-FB_MISC_24,non_blocked
(146)-Locked menu contents-FB_MISC_25,non_blocked
(147)-Locked menu contents-FB_MISC_26,non_blocked
(148)-Locked menu contents-FB_MISC_27,non_blocked
(149)-Locked menu contents-FB_MISC_28,non_blocked
(150)-Locked menu contents-FB_MISC_29,non_blocked
(151)-Locked menu contents-FB_MISC_30,non_blocked
(152)-Locked menu contents-FB_MISC_31,non_blocked
(153)-Locked menu contents-FB_MISC_32,non_blocked
(154)-Locked menu contents-FB_MISC_33,non_blocked
(155)-Locked menu contents-FB_MISC_34,non_blocked
(156)-Locked menu contents-FB_MISC_35,non_blocked
(157)-Locked menu contents-FB_MISC_36,non_blocked
(158)-Locked menu contents-FB_MISC_37,non_blocked
(159)-Locked menu contents-FB_MISC_38,non_blocked
(160)-Locked menu contents-FB_MISC_39,non_blocked
(161)-Locked menu contents-FB_MISC_40,non_blocked
(162)-Locked menu contents-FB_MISC_41,non_blocked
(163)-Locked menu contents-FB_MISC_42,non_blocked
(164)-Locked menu contents-FB_MISC_43,non_blocked
(165)-Locked menu contents-FB_MISC_44,non_blocked
(166)-Locked menu contents-FB_MISC_45,non_blocked
(167)-Locked menu contents-FB_MISC_46,non_blocked
(168)-Locked menu contents-FB_MISC_47,non_blocked

Menu entries for mobile online services,activated
Microphone sensitivity,0 dB

Number 1 (roaming) for roadside assistance,FF FF FF FF FF FF FF FF FF FF FF
FF FF FF FF FF FF FF FF FF FF FF

Number 1 for Info call,FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
FF FF FF FF

Number 1 for roadside assistance,FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
FF FF FF FF FF FF FF

Number 1 for roadside assistance,FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
FF FF FF FF FF FF FF

Number 2 for Info call,FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
FF FF FF FF

Number 2 for roadside assistance,FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
FF FF FF FF FF FF FF

(1)-Parameter 2 for connection transfer (UMTS)-Scan Tune Level 2G,0

(2)-Parameter 2 for connection transfer (UMTS)-Scan Tune Level 3G,0

(1)-Parameter for connection transfer (UMTS)-1E_EcLo,0

(2)-Parameter for connection transfer (UMTS)-1E_RSCP,15

adpmap-5f-8S0-035-049_MIB2

(3)-Parameter for connection transfer (UMTS)-1F_EcLo,0
(4)-Parameter for connection transfer (UMTS)-1F_RSCP,15
(5)-Parameter for connection transfer (UMTS)-3A_EcLo,0
(6)-Parameter for connection transfer (UMTS)-3A_RSCP,8
(7)-Parameter for connection transfer (UMTS)-2D_EcLo,0
(8)-Parameter for connection transfer (UMTS)-2D_RSCP,11
Production mode,00 00 00
(1)-Regional codes-Parameter_Set_DVD_Region_Code,2
(2)-Regional codes-Parameter_Set_BlueRay_System_Region_Code,2
Selection of release codes for a SWaP function,FF FF FF FF
Sporadic ring break detection,Visual
Summertime-automatic,automatic
(1)-Surroundings display; virtual camera positions-,0
(2)-Surroundings display; virtual camera positions-,0
(3)-Surroundings display; virtual camera positions-,0
(4)-Surroundings display; virtual camera positions-,0
(5)-Surroundings display; virtual camera positions-,0
(6)-Surroundings display; virtual camera positions-,0
(7)-Surroundings display; virtual camera positions-,0
(8)-Surroundings display; virtual camera positions-,0
(9)-Surroundings display; virtual camera positions-,0
(10)-Surroundings display; virtual camera positions-,0
(11)-Surroundings display; virtual camera positions-,0
(12)-Surroundings display; virtual camera positions-,0
(13)-Surroundings display; virtual camera positions-,0
(14)-Surroundings display; virtual camera positions-,0
(15)-Surroundings display; virtual camera positions-,0
(16)-Surroundings display; virtual camera positions-,0
(17)-Surroundings display; virtual camera positions-,0
(18)-Surroundings display; virtual camera positions-,0
(19)-Surroundings display; virtual camera positions-,0
(20)-Surroundings display; virtual camera positions-,0
(21)-Surroundings display; virtual camera positions-,0
(22)-Surroundings display; virtual camera positions-,0
(23)-Surroundings display; virtual camera positions-,0
(24)-Surroundings display; virtual camera positions-,0
(25)-Surroundings display; virtual camera positions-,0
(26)-Surroundings display; virtual camera positions-,0
(27)-Surroundings display; virtual camera positions-,0
(28)-Surroundings display; virtual camera positions-,0
(29)-Surroundings display; virtual camera positions-,0
(30)-Surroundings display; virtual camera positions-,0
(31)-Surroundings display; virtual camera positions-,0
(32)-Surroundings display; virtual camera positions-,0
(33)-Surroundings display; virtual camera positions-,0
(34)-Surroundings display; virtual camera positions-,0
(35)-Surroundings display; virtual camera positions-,0
(36)-Surroundings display; virtual camera positions-,0
(37)-Surroundings display; virtual camera positions-,0
(38)-Surroundings display; virtual camera positions-,0
(39)-Surroundings display; virtual camera positions-,0
(40)-Surroundings display; virtual camera positions-,0

adpmap-5f-850-035-049_MIB2

(41)-Surroundings display; virtual camera positions-,0
(42)-Surroundings display; virtual camera positions-,0
(43)-Surroundings display; virtual camera positions-,-18688
(44)-Surroundings display; virtual camera positions-,0
(45)-Surroundings display; virtual camera positions-,0
(46)-Surroundings display; virtual camera positions-,3128321
(47)-Surroundings display; virtual camera positions-,256
(48)-Surroundings display; virtual camera positions-,2628609
(49)-Surroundings display; virtual camera positions-,16777216
(50)-Surroundings display; virtual camera positions-,1
(51)-Surroundings display; virtual camera positions-,3299889
(52)-Surroundings display; virtual camera positions-,0
(53)-Surroundings display; virtual camera positions-,12570624
(54)-Surroundings display; virtual camera positions-,2859265
(55)-Surroundings display; virtual camera positions-,15077120
(56)-Surroundings display; virtual camera positions-,18080716063440896
(57)-Surroundings display; virtual camera positions-,65536
(58)-Surroundings display; virtual camera positions-,-18175
(59)-Surroundings display; virtual camera positions-,0
(60)-Surroundings display; virtual camera positions-,959987968
(61)-Surroundings display; virtual camera positions-,12483337
(62)-Surroundings display; virtual camera positions-,11364606
(63)-Surroundings display; virtual camera positions-,16777216
(64)-Surroundings display; virtual camera positions-,11368702
(65)-Surroundings display; virtual camera positions-,256
(66)-Surroundings display; virtual camera positions-,0
(67)-Surroundings display; virtual camera positions-,5287937
(68)-Surroundings display; virtual camera positions-,4063232
(69)-Surroundings display; virtual camera positions-,256
(70)-Surroundings display; virtual camera positions-,18019591410286592
(71)-Surroundings display; virtual camera positions-,256
(72)-Surroundings display; virtual camera positions-,0
(73)-Surroundings display; virtual camera positions-,-20479
(74)-Surroundings display; virtual camera positions-,4063232
(75)-Surroundings display; virtual camera positions-,0
(76)-Surroundings display; virtual camera positions-,12032769
(77)-Surroundings display; virtual camera positions-,16842752
(78)-Surroundings display; virtual camera positions-,-7935
(79)-Surroundings display; virtual camera positions-,22272
(80)-Surroundings display; virtual camera positions-,10227713
(81)-Surroundings display; virtual camera positions-,22272
(82)-Surroundings display; virtual camera positions-,2140291126
(83)-Surroundings display; virtual camera positions-,0
(84)-Surroundings display; virtual camera positions-,118111179505664
(85)-Surroundings display; virtual camera positions-,5582848
(86)-Surroundings display; virtual camera positions-,2367488
(87)-Surroundings display; virtual camera positions-,-512
(88)-Surroundings display; virtual camera positions-,0
(89)-Surroundings display; virtual camera positions-,0
(90)-Surroundings display; virtual camera positions-,9203457
(91)-Surroundings display; virtual camera positions-,14865902662912
(92)-Surroundings display; virtual camera positions-,-4607

adpmap-5f-850-035-049_MIB2

(93)-Surroundings display; virtual camera positions-,7941641
(94)-Surroundings display; virtual camera positions-,12290
(95)-Surroundings display; virtual camera positions-,6838784
(96)-Surroundings display; virtual camera positions-,0
(97)-Surroundings display; virtual camera positions-,571112192
(98)-Surroundings display; virtual camera positions-,24019717854658560
(99)-Surroundings display; virtual camera positions-,0
(100)-Surroundings display; virtual camera positions-,5582848
(101)-Surroundings display; virtual camera positions-,14173184
(102)-Surroundings display; virtual camera positions-,3684352
(103)-Surroundings display; virtual camera positions-,387328
(104)-Surroundings display; virtual camera positions-,8191745
(105)-Surroundings display; virtual camera positions-,25690013696
Telephone,Data & language service active
Telephone data services,On
(1)-Vehicle configuration-VZAPro,On
(2)-Vehicle configuration-online_POI,On
(3)-Vehicle configuration-online_POI_voice,On
(4)-Vehicle configuration-online_portal_browser_services,On
(5)-Vehicle configuration-online_navigation,On
(6)-Vehicle configuration-online_street_view,On
(7)-Vehicle configuration-WIFI_Hotspot,On
(8)-Vehicle configuration-my_audi,OFF
(9)-Vehicle configuration-picture_navi,On
(10)-Vehicle configuration-online_dictation,OFF
(11)-Vehicle configuration-remote_HMI,OFF
(12)-Vehicle configuration-advanced_range_display,OFF
(13)-Vehicle configuration-gracenote_online_coverarts,On
(14)-Vehicle configuration-gracenote_online_other,On
(15)-Vehicle configuration-gracenote_local_coverarts,On
(16)-Vehicle configuration-gracenote_local_other,On
(17)-Vehicle configuration-UPnP,On
(18)-Vehicle configuration-OPS_display_in_dash_board_display_unit,On
(19)-Vehicle configuration-Joker_button_1,Not Present
(20)-Vehicle configuration-Joker_button_2,Not Present
(21)-Vehicle configuration-LTE_modul,activated
(22)-Vehicle configuration-Support_second_phone,On
(23)-Vehicle configuration-Support_of_threeway_calling,On
(24)-Vehicle configuration-Dtmf_without_active_call,On
(25)-Vehicle configuration-Support_for_response_and_hold,On
(26)-Vehicle configuration-Sim_card_mode_switch,present
(27)-Vehicle configuration-Phone_module_operation_mode,Data & language service active
(28)-Vehicle configuration-PSD_Protocol_Version,PSD_1.5
(29)-Vehicle configuration-RVC_video_input,FBAS
(30)-Vehicle configuration-Station_Logo_DB_Mode,1
(31)-Vehicle configuration-TPEG_availability,On
(32)-Vehicle configuration-VZO,On
(33)-Vehicle configuration-LGI,OFF
(34)-Vehicle configuration-ProbeCar_vzo,OFF
(35)-Vehicle configuration-online_media,On
(36)-Vehicle configuration-ProbeCar_lgi,OFF

adpmap-5f-8S0-035-049_MIB2

(37)-Vehicle configuration-NMH_stopwatch,OFF
(38)-Vehicle configuration-Google_GAL,On
(39)-Vehicle configuration-Apple_DIO,On
(40)-Vehicle configuration-UOTA,OFF
(41)-Vehicle configuration-WiFi_Client_HMI,OFF
(42)-Vehicle configuration-RSE_software_component,activated
(43)-Vehicle configuration-SDS_Region_Flag,REGION_ROW_SOUTHAMERICA
(1)-Vehicle dimensions-Length,0 mm
(2)-Vehicle dimensions-Width,0 mm
(3)-Vehicle dimensions-Height,0 mm
(1)-Voice operation for telephone-apple_device,installed
(2)-Voice operation for telephone-other_devices,not installed
Wheel circ.,0 mm
Wheel pulse,0
WLAN,On
(1)-Audio_Management_Audio_Delay_Lines_Gen2-Main_Unit_Delay_On_Off,OFF
(2)-Audio_Management_Audio_Delay_Lines_Gen2-Main_Unit_Delay_Time,0.00 ms
(3)-Audio_Management_Audio_Delay_Lines_Gen2-Amplifier_Delay_On_Off,OFF
(4)-Audio_Management_Audio_Delay_Lines_Gen2-Amplifier_Delay_Time,0.00 ms
(5)-Audio_Management_Audio_Delay_Lines_Gen2-Headphone_Delay_On_Off,OFF
(6)-Audio_Management_Audio_Delay_Lines_Gen2-Headphone_Delay_Time,0.00 ms
(7)-Audio_Management_Audio_Delay_Lines_Gen2-Headphone_wireless_Delay_On_Off,OFF
(8)-Audio_Management_Audio_Delay_Lines_Gen2-Headphone_wireless_Delay_Time,0.00 ms
ms
Audio_Managment_Soundset_Menu,OFF
BAP_Debug_Mode_Release,not_released
(1)-Car_Function_Adaptations_Gen2-menu_display_ACC,activated
(2)-Car_Function_Adaptations_Gen2-menu_display_ACC_operation_clamp_15_off,not activated
(3)-Car_Function_Adaptations_Gen2-menu_display_ACC_over_threshold_high,not activated
(4)-Car_Function_Adaptations_Gen2-menu_display_ACC_standstill,not activated
(5)-Car_Function_Adaptations_Gen2-menu_display_ACC_after_disclaimer,not activated
(6)-Car_Function_Adaptations_Gen2-menu_display_ambient_illumination,activated
(7)-Car_Function_Adaptations_Gen2-menu_display_ambient_illumination_clamp_15_off,not activated
(8)-Car_Function_Adaptations_Gen2-menu_display_ambient_illumination_over_threshold_high,not activated
(9)-Car_Function_Adaptations_Gen2-menu_display_ambient_illumination_standstill,not activated
(10)-Car_Function_Adaptations_Gen2-menu_display_ambient_illumination_after_disclaimer,not activated
(11)-Car_Function_Adaptations_Gen2-menu_display_pdc,activated
(12)-Car_Function_Adaptations_Gen2-menu_display_pdc_clamp_15_off,not activated
(13)-Car_Function_Adaptations_Gen2-menu_display_pdc_over_threshold_high,not activated
(14)-Car_Function_Adaptations_Gen2-menu_display_pdc_standstill,not activated
(15)-Car_Function_Adaptations_Gen2-menu_display_pdc_after_disclaimer,not activated
(16)-Car_Function_Adaptations_Gen2-menu_display_awv,activated
(17)-Car_Function_Adaptations_Gen2-menu_display_awv_clamp_15_off,not activated

- (18)-Car_Function_Adaptations_Gen2-menu_display_awv_over_threshold_high,not activated
- (19)-Car_Function_Adaptations_Gen2-menu_display_awv_standstill,not activated
- (20)-Car_Function_Adaptations_Gen2-menu_display_awv_after_disclaimer,not activated
- (21)-Car_Function_Adaptations_Gen2-menu_display_Lane_Departure_Warning,activated
- (22)-Car_Function_Adaptations_Gen2-menu_display_Lane_Departure_Warning_clamp_15_off,not activated
- (23)-Car_Function_Adaptations_Gen2-menu_display_Lane_Departure_Warning_over_threshold_high,activated
- (24)-Car_Function_Adaptations_Gen2-menu_display_Lane_Departure_Warning_standstill,not activated
- (25)-Car_Function_Adaptations_Gen2-menu_display_Lane_Departure_Warning_after_disclaimer,not activated
- (26)-Car_Function_Adaptations_Gen2-menu_display_lane_assistant,not activated
- (27)-Car_Function_Adaptations_Gen2-menu_display_lane_assistant_clamp_15_off,not activated
- (28)-Car_Function_Adaptations_Gen2-menu_display_lane_assistant_over_threshold_high,not activated
- (29)-Car_Function_Adaptations_Gen2-menu_display_lane_assistant_standstill,not activated
- (30)-Car_Function_Adaptations_Gen2-menu_display_lane_assistant_after_disclaimer,not activated
- (31)-Car_Function_Adaptations_Gen2-menu_display_exterior_illumination,activated
- (32)-Car_Function_Adaptations_Gen2-menu_display_exterior_illumination_clamp_15_off,not activated
- (33)-Car_Function_Adaptations_Gen2-menu_display_exterior_illumination_over_threshold_high,not activated
- (34)-Car_Function_Adaptations_Gen2-menu_display_exterior_illumination_standstill,not activated
- (35)-Car_Function_Adaptations_Gen2-menu_display_exterior_illumination_after_disclaimer,not activated
- (36)-Car_Function_Adaptations_Gen2-menu_display_windows,activated
- (37)-Car_Function_Adaptations_Gen2-menu_display_windows_clamp_15_off,not activated
- (38)-Car_Function_Adaptations_Gen2-menu_display_windows_over_threshold_high,activated
- (39)-Car_Function_Adaptations_Gen2-menu_display_windows_standstill,not activated
- (40)-Car_Function_Adaptations_Gen2-menu_display_windows_after_disclaimer,not activated
- (41)-Car_Function_Adaptations_Gen2-menu_display_clima_configuration,activated
- (42)-Car_Function_Adaptations_Gen2-menu_display_clima_configuration_clamp_15_off,not activated
- (43)-Car_Function_Adaptations_Gen2-menu_display_clima_configuration_over_threshold_high,not activated
- (44)-Car_Function_Adaptations_Gen2-menu_display_clima_configuration_standstill,not activated
- (45)-Car_Function_Adaptations_Gen2-menu_display_clima_configuration_after_disclaimer,not activated
- (46)-Car_Function_Adaptations_Gen2-menu_display_auxiliary_heating,not activated

(47)-Car_Function_Adaptations_Gen2-menu_display_auxiliary_heating_clamp_15_off,not activated
(48)-Car_Function_Adaptations_Gen2-menu_display_auxiliary_heating_over_threshold_high,not activated
(49)-Car_Function_Adaptations_Gen2-menu_display_auxiliary_heating_standstill,not activated
(50)-Car_Function_Adaptations_Gen2-menu_display_auxiliary_heating_after_disclaimer,not activated
(51)-Car_Function_Adaptations_Gen2-menu_display_board_computer,activated
(52)-Car_Function_Adaptations_Gen2-menu_display_board_computer_clamp_15_off,not activated
(53)-Car_Function_Adaptations_Gen2-menu_display_board_computer_over_threshold_high,activated
(54)-Car_Function_Adaptations_Gen2-menu_display_board_computer_standstill,not activated
(55)-Car_Function_Adaptations_Gen2-menu_display_board_computer_after_disclaimer,not activated
(56)-Car_Function_Adaptations_Gen2-menu_display_rdk,activated
(57)-Car_Function_Adaptations_Gen2-menu_display_rdk_clamp_15_off,not activated
(58)-Car_Function_Adaptations_Gen2-menu_display_rdk_over_threshold_high,not activated
(59)-Car_Function_Adaptations_Gen2-menu_display_rdk_standstill,not activated
(60)-Car_Function_Adaptations_Gen2-menu_display_rdk_after_disclaimer,not activated
(61)-Car_Function_Adaptations_Gen2-menu_display_wiper,activated
(62)-Car_Function_Adaptations_Gen2-menu_display_wiper_clamp_15_off,not activated

(63)-Car_Function_Adaptations_Gen2-menu_display_wiper_over_threshold_high,not activated
(64)-Car_Function_Adaptations_Gen2-menu_display_wiper_standstill,not activated
(65)-Car_Function_Adaptations_Gen2-menu_display_wiper_after_disclaimer,not activated
(66)-Car_Function_Adaptations_Gen2-menu_display_sia,activated
(67)-Car_Function_Adaptations_Gen2-menu_display_sia_clamp_15_off,not activated
(68)-Car_Function_Adaptations_Gen2-menu_display_sia_over_threshold_high,not activated
(69)-Car_Function_Adaptations_Gen2-menu_display_sia_standstill,not activated
(70)-Car_Function_Adaptations_Gen2-menu_display_sia_after_disclaimer,not activated
(71)-Car_Function_Adaptations_Gen2-menu_display_seat_configuration,not activated

(72)-Car_Function_Adaptations_Gen2-menu_display_seat_configuration_clamp_15_off,not activated
(73)-Car_Function_Adaptations_Gen2-menu_display_seat_configuration_over_threshold_high,not activated
(74)-Car_Function_Adaptations_Gen2-menu_display_seat_configuration_standstill,not activated
(75)-Car_Function_Adaptations_Gen2-menu_display_seat_configuration_after_disclaimer,not activated
(76)-Car_Function_Adaptations_Gen2-menu_display_central_locking,activated
(77)-Car_Function_Adaptations_Gen2-menu_display_central_locking_clamp_15_off,not activated

(78)-Car_Function_Adaptations_Gen2-menu_display_central_locking_over_threshold_high,not activated
(79)-Car_Function_Adaptations_Gen2-menu_display_central_locking_standstill,not activated
(80)-Car_Function_Adaptations_Gen2-menu_display_central_locking_after_disclaimer,not activated
(81)-Car_Function_Adaptations_Gen2-menu_display_compass,activated
(82)-Car_Function_Adaptations_Gen2-menu_display_compass_clamp_15_off,not activated
(83)-Car_Function_Adaptations_Gen2-menu_display_compass_over_threshold_high,not activated
(84)-Car_Function_Adaptations_Gen2-menu_display_compass_standstill,not activated

(85)-Car_Function_Adaptations_Gen2-menu_display_compass_after_disclaimer,not activated
(86)-Car_Function_Adaptations_Gen2-menu_display_charisma,activated
(87)-Car_Function_Adaptations_Gen2-menu_display_charisma_clamp_15_off,not activated
(88)-Car_Function_Adaptations_Gen2-menu_display_charisma_over_threshold_high,not activated
(89)-Car_Function_Adaptations_Gen2-menu_display_charisma_standstill,not activated
(90)-Car_Function_Adaptations_Gen2-menu_display_charisma_after_disclaimer,not activated
(91)-Car_Function_Adaptations_Gen2-menu_display_oil_level,activated
(92)-Car_Function_Adaptations_Gen2-menu_display_oil_level_clamp_15_off,not activated
(93)-Car_Function_Adaptations_Gen2-menu_display_oil_level_over_threshold_high,not activated
(94)-Car_Function_Adaptations_Gen2-menu_display_oil_level_standstill,not activated
(95)-Car_Function_Adaptations_Gen2-menu_display_oil_level_after_disclaimer,not activated
(96)-Car_Function_Adaptations_Gen2-menu_display_vin,activated
(97)-Car_Function_Adaptations_Gen2-menu_display_vin_clamp_15_off,not activated
(98)-Car_Function_Adaptations_Gen2-menu_display_vin_over_threshold_high,not activated
(99)-Car_Function_Adaptations_Gen2-menu_display_vin_standstill,not activated
(100)-Car_Function_Adaptations_Gen2-menu_display_vin_after_disclaimer,not activated
(101)-Car_Function_Adaptations_Gen2-menu_display_clock,activated
(102)-Car_Function_Adaptations_Gen2-menu_display_clock_clamp_15_off,not activated
(103)-Car_Function_Adaptations_Gen2-menu_display_clock_over_threshold_high,not activated
(104)-Car_Function_Adaptations_Gen2-menu_display_clock_standstill,not activated
(105)-Car_Function_Adaptations_Gen2-menu_display_clock_after_disclaimer,not activated
(106)-Car_Function_Adaptations_Gen2-menu_display_air_damper,activated
(107)-Car_Function_Adaptations_Gen2-menu_display_air_damper_clamp_15_off,not activated
(108)-Car_Function_Adaptations_Gen2-menu_display_air_damper_over_threshold_high,

not activated

(109)-Car_Function_Adaptations_Gen2-menu_display_air_damper_standstill,not activated

(110)-Car_Function_Adaptations_Gen2-menu_display_air_damper_after_disclaimer,not activated

(111)-Car_Function_Adaptations_Gen2-menu_display_headup_display,not activated

(112)-Car_Function_Adaptations_Gen2-menu_display_headup_display_clamp_15_off,not activated

(113)-Car_Function_Adaptations_Gen2-menu_display_headup_display_over_threshold_high,not activated

(114)-Car_Function_Adaptations_Gen2-menu_display_headup_display_standstill,not activated

(115)-Car_Function_Adaptations_Gen2-menu_display_headup_display_after_disclaimer,not activated

(116)-Car_Function_Adaptations_Gen2-menu_display_central_unit_master,activated

(117)-Car_Function_Adaptations_Gen2-menu_display_central_unit_master_clamp_15_off,not activated

(118)-Car_Function_Adaptations_Gen2-menu_display_central_unit_master_over_threshold_high,not activated

(119)-Car_Function_Adaptations_Gen2-menu_display_central_unit_master_standstill,not activated

(120)-Car_Function_Adaptations_Gen2-menu_display_central_unit_master_after_disclaimer,not activated

(121)-Car_Function_Adaptations_Gen2-menu_display_hybrid,not activated

(122)-Car_Function_Adaptations_Gen2-menu_display_hybrid_clamp_15_off,not activated

(123)-Car_Function_Adaptations_Gen2-menu_display_hybrid_over_threshold_high,not activated

(124)-Car_Function_Adaptations_Gen2-menu_display_hybrid_standstill,not activated

(125)-Car_Function_Adaptations_Gen2-menu_display_hybrid_after_disclaimer,not activated

(126)-Car_Function_Adaptations_Gen2-menu_display_ugdo,activated

(127)-Car_Function_Adaptations_Gen2-menu_display_ugdo_clamp_15_off,not activated

(128)-Car_Function_Adaptations_Gen2-menu_display_ugdo_over_threshold_high,not activated

(129)-Car_Function_Adaptations_Gen2-menu_display_ugdo_standstill,not activated

(130)-Car_Function_Adaptations_Gen2-menu_display_ugdo_after_disclaimer,not activated

(131)-Car_Function_Adaptations_Gen2-menu_display_night_vision,not activated

(132)-Car_Function_Adaptations_Gen2-menu_display_night_vision_clamp_15_off,not activated

(133)-Car_Function_Adaptations_Gen2-menu_display_night_vision_over_threshold_high,not activated

(134)-Car_Function_Adaptations_Gen2-menu_display_night_vision_standstill,not activated

(135)-Car_Function_Adaptations_Gen2-menu_display_night_vision_after_disclaimer,not activated

(136)-Car_Function_Adaptations_Gen2-menu_display_side_view,not activated

(137)-Car_Function_Adaptations_Gen2-menu_display_side_view_clamp_15_off,not activated

(138)-Car_Function_Adaptations_Gen2-menu_display_side_view_over_threshold_high,not activated
(139)-Car_Function_Adaptations_Gen2-menu_display_side_view_standstill,not activated
(140)-Car_Function_Adaptations_Gen2-menu_display_side_view_after_disclaimer,not activated
(141)-Car_Function_Adaptations_Gen2-menu_display_reversible_belt_pre_load,activated
(142)-Car_Function_Adaptations_Gen2-menu_display_reversible_belt_pre_load_clamp_15_off,not activated
(143)-Car_Function_Adaptations_Gen2-menu_display_reversible_belt_pre_load_over_threshold_high,not activated
(144)-Car_Function_Adaptations_Gen2-menu_display_reversible_belt_pre_load_standstill,not activated
(145)-Car_Function_Adaptations_Gen2-menu_display_reversible_belt_pre_load_after_disclaimer,not activated
(146)-Car_Function_Adaptations_Gen2-menu_display_MFL_jocker,not activated
(147)-Car_Function_Adaptations_Gen2-menu_display_MFL_jocker_clamp_15_off,not activated
(148)-Car_Function_Adaptations_Gen2-menu_display_MFL_jocker_over_threshold_high,not activated
(149)-Car_Function_Adaptations_Gen2-menu_display_MFL_jocker_standstill,not activated
(150)-Car_Function_Adaptations_Gen2-menu_display_MFL_jocker_after_disclaimer,not activated
(151)-Car_Function_Adaptations_Gen2-menu_display_road_sign_identification,activated
(152)-Car_Function_Adaptations_Gen2-menu_display_road_sign_identification_clamp_15_off,not activated
(153)-Car_Function_Adaptations_Gen2-menu_display_road_sign_identification_over_threshold_high,activated
(154)-Car_Function_Adaptations_Gen2-menu_display_road_sign_identification_standstill,not activated
(155)-Car_Function_Adaptations_Gen2-menu_display_road_sign_identification_after_disclaimer,not activated
(156)-Car_Function_Adaptations_Gen2-menu_display_attention_identification,not activated
(157)-Car_Function_Adaptations_Gen2-menu_display_attention_identification_clamp_15_off,not activated
(158)-Car_Function_Adaptations_Gen2-menu_display_attention_identification_over_threshold_high,not activated
(159)-Car_Function_Adaptations_Gen2-menu_display_attention_identification_standstill,not activated
(160)-Car_Function_Adaptations_Gen2-menu_display_attention_identification_after_disclaimer,not activated
(161)-Car_Function_Adaptations_Gen2-menu_display_adaptive_key,not activated
(162)-Car_Function_Adaptations_Gen2-menu_display_adaptive_key_clamp_15_off,not activated
(163)-Car_Function_Adaptations_Gen2-menu_display_adaptive_key_over_threshold_high,not activated
(164)-Car_Function_Adaptations_Gen2-menu_display_adaptive_key_standstill,not activated

(165)-Car_Function_Adaptations_Gen2-menu_display_adaptive_key_after_disclaimer,not activated
(166)-Car_Function_Adaptations_Gen2-menu_display_car_mirror,not activated
(167)-Car_Function_Adaptations_Gen2-menu_display_car_mirror_clamp_15_off,not activated
(168)-Car_Function_Adaptations_Gen2-menu_display_car_mirror_over_threshold_high,not activated
(169)-Car_Function_Adaptations_Gen2-menu_display_car_mirror_standstill,not activated
(170)-Car_Function_Adaptations_Gen2-menu_display_car_mirror_after_disclaimer,not activated
(171)-Car_Function_Adaptations_Gen2-menu_display_driving_school,not activated
(172)-Car_Function_Adaptations_Gen2-menu_display_driving_school_clamp_15_off,not activated
(173)-Car_Function_Adaptations_Gen2-menu_display_driving_school_over_threshold_high,not activated
(174)-Car_Function_Adaptations_Gen2-menu_display_driving_school_standstill,not activated
(175)-Car_Function_Adaptations_Gen2-menu_display_driving_school_after_disclaimer,not activated
(176)-Car_Function_Adaptations_Gen2-menu_display_weariness_recognition,not activated
(177)-Car_Function_Adaptations_Gen2-menu_display_weariness_recognition_clamp_15_off,not activated
(178)-Car_Function_Adaptations_Gen2-menu_display_weariness_recognition_over_threshold_high,not activated
(179)-Car_Function_Adaptations_Gen2-menu_display_weariness_recognition_standstill,not activated
(180)-Car_Function_Adaptations_Gen2-menu_display_weariness_recognition_after_disclaimer,not activated
(181)-Car_Function_Adaptations_Gen2-menu_display_BCmE,not activated
(182)-Car_Function_Adaptations_Gen2-menu_display_BCmE_clamp_15_off,not activated

(183)-Car_Function_Adaptations_Gen2-menu_display_BCmE_over_threshold_high,not activated
(184)-Car_Function_Adaptations_Gen2-menu_display_BCmE_standstill,not activated
(185)-Car_Function_Adaptations_Gen2-menu_display_BCmE_after_disclaimer,not activated
(186)-Car_Function_Adaptations_Gen2-menu_display_user_eco_rating,not activated
(187)-Car_Function_Adaptations_Gen2-menu_display_user_eco_rating_clamp_15_off,not activated
(188)-Car_Function_Adaptations_Gen2-menu_display_user_eco_rating_over_threshold_high,not activated
(189)-Car_Function_Adaptations_Gen2-menu_display_user_eco_rating_standstill,not activated
(190)-Car_Function_Adaptations_Gen2-menu_display_user_eco_rating_after_disclaimer,not activated
(191)-Car_Function_Adaptations_Gen2-menu_display_Brake_Function,not activated
(192)-Car_Function_Adaptations_Gen2-menu_display_Brake_Function_clamp_15_off,not activated
(193)-Car_Function_Adaptations_Gen2-menu_display_Brake_Function_over_threshold_high,not activated

(194)-Car_Function_Adaptations_Gen2-menu_display_Brake_Function_standstill,not activated
(195)-Car_Function_Adaptations_Gen2-menu_display_Brake_Function_after_disclaimer,not activated
(196)-Car_Function_Adaptations_Gen2-menu_display_Start_Stop_reasons,not activated
(197)-Car_Function_Adaptations_Gen2-menu_display_Start_Stop_reasons_clamp_15_off,not activated
(198)-Car_Function_Adaptations_Gen2-menu_display_Start_Stop_reasons_over_threshold_high,not activated
(199)-Car_Function_Adaptations_Gen2-menu_display_Start_Stop_reasons_standstill,not activated
(200)-Car_Function_Adaptations_Gen2-menu_display_Start_Stop_reasons_after_disclaimer,not activated
(201)-Car_Function_Adaptations_Gen2-menu_display_angle_of_slope,not activated
(202)-Car_Function_Adaptations_Gen2-menu_display_angle_of_slope_clamp_15_off,not activated
(203)-Car_Function_Adaptations_Gen2-menu_display_angle_of_slope_over_threshold_high,not activated
(204)-Car_Function_Adaptations_Gen2-menu_display_angle_of_slope_standstill,not activated
(205)-Car_Function_Adaptations_Gen2-menu_display_angle_of_slope_after_disclaimer,not activated
(206)-Car_Function_Adaptations_Gen2-menu_display_battery_management,not activated
(207)-Car_Function_Adaptations_Gen2-menu_display_battery_management_clamp_15_off,not activated
(208)-Car_Function_Adaptations_Gen2-menu_display_battery_management_over_threshold_high,not activated
(209)-Car_Function_Adaptations_Gen2-menu_display_battery_management_standstill,not activated
(210)-Car_Function_Adaptations_Gen2-menu_display_battery_management_after_disclaimer,not activated
(211)-Car_Function_Adaptations_Gen2-menu_display_RearSeatEntertainment,not activated
(212)-Car_Function_Adaptations_Gen2-menu_display_RearSeatEntertainment_clamp_15_off,not activated
(213)-Car_Function_Adaptations_Gen2-menu_display_RearSeatEntertainment_over_threshold_high,not activated
(214)-Car_Function_Adaptations_Gen2-menu_display_RearSeatEntertainment_standstill,not activated
(215)-Car_Function_Adaptations_Gen2-menu_display_RearSeatEntertainment_after_disclaimer,not activated
(216)-Car_Function_Adaptations_Gen2-menu_display_special_functions,not activated

(217)-Car_Function_Adaptations_Gen2-menu_display_special_functions_clamp_15_off,not activated
(218)-Car_Function_Adaptations_Gen2-menu_display_special_functions_over_threshold_high,not activated
(219)-Car_Function_Adaptations_Gen2-menu_display_special_functions_standstill,not activated
(220)-Car_Function_Adaptations_Gen2-menu_display_special_functions_after_disclaimer,not activated

mer,not activated

(221)-Car_Function_Adaptations_Gen2-menu_display_trailer_assistant,not activated

(222)-Car_Function_Adaptations_Gen2-menu_display_trailer_assistant_clamp_15_off,not activated

(223)-Car_Function_Adaptations_Gen2-menu_display_trailer_assistant_over_threshold_high,not activated

(224)-Car_Function_Adaptations_Gen2-menu_display_trailer_assistant_standstill,not activated

(225)-Car_Function_Adaptations_Gen2-menu_display_trailer_assistant_after_disclaimer,not activated

(226)-Car_Function_Adaptations_Gen2-menu_display_TV_tuner,not activated

(227)-Car_Function_Adaptations_Gen2-menu_display_TV_tuner_clamp_15_off,not activated

(228)-Car_Function_Adaptations_Gen2-menu_display_TV_tuner_over_threshold_high,not activated

(229)-Car_Function_Adaptations_Gen2-menu_display_TV_tuner_standstill,not activated

(230)-Car_Function_Adaptations_Gen2-menu_display_TV_tuner_after_disclaimer,not activated

(231)-Car_Function_Adaptations_Gen2-menu_auxiliary_climatization,not activated

(232)-Car_Function_Adaptations_Gen2-menu_auxiliary_climatization_clamp_15_off,not activated

(233)-Car_Function_Adaptations_Gen2-menu_auxiliary_climatization_over_threshold_high,not activated

(234)-Car_Function_Adaptations_Gen2-menu_auxiliary_climatization_standstill,not activated

(235)-Car_Function_Adaptations_Gen2-menu_auxiliary_climatization_after_disclaimer,not activated

(236)-Car_Function_Adaptations_Gen2-menu_display_Pedestrian_Assist,not activated

(237)-Car_Function_Adaptations_Gen2-menu_display_Pedestrian_Assist_clamp_15_off,not activated

(238)-Car_Function_Adaptations_Gen2-menu_display_Pedestrian_Assist_over_threshold_high,not activated

(239)-Car_Function_Adaptations_Gen2-menu_display_Pedestrian_Assist_standstill,not activated

(240)-Car_Function_Adaptations_Gen2-menu_display_Pedestrian_Assist_after_disclaimer,not activated

(241)-Car_Function_Adaptations_Gen2-menu_display_Seat_Pneumatic,not activated

(242)-Car_Function_Adaptations_Gen2-menu_display_Seat_Pneumatic_clamp_15_off,not activated

(243)-Car_Function_Adaptations_Gen2-menu_display_Seat_Pneumatic_over_threshold_high,not activated

(244)-Car_Function_Adaptations_Gen2-menu_display_Seat_Pneumatic_standstill,not activated

(245)-Car_Function_Adaptations_Gen2-menu_display_Seat_Pneumatic_after_disclaimer,not activated

(246)-Car_Function_Adaptations_Gen2-menu_display_Curve_Assist,not activated

(247)-Car_Function_Adaptations_Gen2-menu_display_Curve_Assist_clamp_15_off,not activated

(248)-Car_Function_Adaptations_Gen2-menu_display_Curve_Assist_over_threshold_high

h,not activated

(249)-Car_Function_Adaptations_Gen2-menu_display_Curve_Assist_standstill,not activated

(250)-Car_Function_Adaptations_Gen2-menu_display_Curve_Assist_after_disclaimer,not activated

(251)-Car_Function_Adaptations_Gen2-menu_display_Ecall,not activated

(252)-Car_Function_Adaptations_Gen2-menu_display_eCall_clamp_15_off,not activated

(253)-Car_Function_Adaptations_Gen2-menu_display_Ecall_over_threshold_high,not activated

(254)-Car_Function_Adaptations_Gen2-menu_display_Ecall_standstill,not activated

(255)-Car_Function_Adaptations_Gen2-menu_display_Ecall_after_disclaimer,not activated

(256)-Car_Function_Adaptations_Gen2-menu_display_ENI,not activated

(257)-Car_Function_Adaptations_Gen2-menu_display_ENI_clamp_15_off,not activated

(258)-Car_Function_Adaptations_Gen2-menu_display_ENI_over_threshold_high,not activated

(259)-Car_Function_Adaptations_Gen2-menu_display_ENI_standstill,not activated

(260)-Car_Function_Adaptations_Gen2-menu_display_ENI_after_disclaimer,not activated

(261)-Car_Function_Adaptations_Gen2-menu_display_SportHMI,not activated

(262)-Car_Function_Adaptations_Gen2-menu_display_SportHMI_clamp_15_off,not activated

(263)-Car_Function_Adaptations_Gen2-menu_display_SportHMI_over_threshold_high,not activated

(264)-Car_Function_Adaptations_Gen2-menu_display_SportHMI_standstill,not activated

(265)-Car_Function_Adaptations_Gen2-menu_display_SportHMI_after_disclaimer,not activated

(266)-Car_Function_Adaptations_Gen2-menu_display_Adblue,not activated

(267)-Car_Function_Adaptations_Gen2-menu_display_Adblue_clamp_15_off,not activated

(268)-Car_Function_Adaptations_Gen2-menu_display_Adblue_over_threshold_high,not activated

(269)-Car_Function_Adaptations_Gen2-menu_display_Adblue_standstill,not activated

(270)-Car_Function_Adaptations_Gen2-menu_display_Adblue_after_disclaimer,not activated

(271)-Car_Function_Adaptations_Gen2-menu_display_ThinkBlue,not activated

(272)-Car_Function_Adaptations_Gen2-menu_display_ThinkBlue_clamp_15_off,not activated

(273)-Car_Function_Adaptations_Gen2-menu_display_ThinkBlue_over_threshold_high,not activated

(274)-Car_Function_Adaptations_Gen2-menu_display_ThinkBlue_standstill,not activated

(275)-Car_Function_Adaptations_Gen2-menu_display_ThinkBlue_after_disclaimer,not activated

(276)-Car_Function_Adaptations_Gen2-menu_display_Efficiency_Assist,not activated

(277)-Car_Function_Adaptations_Gen2-menu_display_Efficiency_Assist_clamp_15_off,not activated

(278)-Car_Function_Adaptations_Gen2-menu_display_Efficiency_Assist_over_threshold

d_high,not activated

(279)-Car_Function_Adaptations_Gen2-menu_display_Efficiency_Assist_standstill,not activated

(280)-Car_Function_Adaptations_Gen2-menu_display_Efficiency_Assist_after_disclaimer,not activated

(1)-Car_Function_List_BAP_Gen2-climatic_master_0x01,activated

(2)-Car_Function_List_BAP_Gen2-climatic_master_0x01_msg_bus,Comfort data bus

(3)-Car_Function_List_BAP_Gen2-climatic_slave_0x02,not activated

(4)-Car_Function_List_BAP_Gen2-climatic_slave_0x02_msg_bus,Comfort data bus

(5)-Car_Function_List_BAP_Gen2-auxiliary_heating_0x03,not activated

(6)-Car_Function_List_BAP_Gen2-auxiliary_heating_0x03_msg_bus,Comfort data bus

(7)-Car_Function_List_BAP_Gen2-headup_displ_0x04,not activated

(8)-Car_Function_List_BAP_Gen2-headup_displ_0x04_msg_bus,Comfort data bus

(9)-Car_Function_List_BAP_Gen2-ACC_0x05,activated

(10)-Car_Function_List_BAP_Gen2-ACC_0x05_msg_bus,Databus extended

(11)-Car_Function_List_BAP_Gen2-air_suspension_0x06,not activated

(12)-Car_Function_List_BAP_Gen2-air_suspension_0x06_msg_bus,Suspension data bus

(13)-Car_Function_List_BAP_Gen2-tire_pressure_system_0x07,activated

(14)-Car_Function_List_BAP_Gen2-tire_pressure_system_0x07_msg_bus,Suspension data bus

(15)-Car_Function_List_BAP_Gen2-interieur_light_0x08,activated

(16)-Car_Function_List_BAP_Gen2-interieur_light_0x08_msg_bus,Comfort data bus

(17)-Car_Function_List_BAP_Gen2-exterieur_light_0x09,activated

(18)-Car_Function_List_BAP_Gen2-exterieur_light_0x09_msg_bus,Comfort data bus

(19)-Car_Function_List_BAP_Gen2-parking_assist_0x0A,activated

(20)-Car_Function_List_BAP_Gen2-parking_assist_0x0A_msg_bus,Terminal 15

(21)-Car_Function_List_BAP_Gen2-VPS_0x0B,not activated

(22)-Car_Function_List_BAP_Gen2-VPS_0x0B_msg_bus,Comfort data bus

(23)-Car_Function_List_BAP_Gen2-wiper_comfort_0x0C,activated

(24)-Car_Function_List_BAP_Gen2-wiper_comfort_0x0C_msg_bus,Comfort data bus

(25)-Car_Function_List_BAP_Gen2-central_locking_0x0D,activated

(26)-Car_Function_List_BAP_Gen2-central_locking_0x0D_msg_bus,Comfort data bus

(27)-Car_Function_List_BAP_Gen2-mirror_0x0E,activated

(28)-Car_Function_List_BAP_Gen2-mirror_0x0E_msg_bus,Comfort data bus

(29)-Car_Function_List_BAP_Gen2-MFA_0x0F,activated

(30)-Car_Function_List_BAP_Gen2-MFA_0x0F_msg_bus,Comfort data bus

(31)-Car_Function_List_BAP_Gen2-driver_seat_0x10,not activated

(32)-Car_Function_List_BAP_Gen2-driver_seat_0x10_msg_bus,Comfort data bus

(33)-Car_Function_List_BAP_Gen2-clock_0x11,activated

(34)-Car_Function_List_BAP_Gen2-clock_0x11_msg_bus,Comfort data bus

(35)-Car_Function_List_BAP_Gen2-service_interval_display_0x12,activated

(36)-Car_Function_List_BAP_Gen2-service_interval_display_0x12_msg_bus,Comfort data bus

(37)-Car_Function_List_BAP_Gen2-unit_master_0x13,activated

(38)-Car_Function_List_BAP_Gen2-unit_master_0x13_msg_bus,Comfort data bus

(39)-Car_Function_List_BAP_Gen2-UGDO_0x14,not activated

(40)-Car_Function_List_BAP_Gen2-UGDO_0x14_msg_bus,Terminal 15

(41)-Car_Function_List_BAP_Gen2-compass_0x15,not activated

(42)-Car_Function_List_BAP_Gen2-compass_0x15_msg_bus,Databus Infotainment

(43)-Car_Function_List_BAP_Gen2-clima_slave_2_0x16,not activated

(44)-Car_Function_List_BAP_Gen2-clima_slave_2_0x16_msg_bus,Comfort data bus

(45)-Car_Function_List_BAP_Gen2-charisma_0x17,activated

adpmap-5f-8S0-035-049_MIB2

- (46)-Car_Function_List_BAP_Gen2-charisma_0x17_msg_bus,Databus Infotainment
- (47)-Car_Function_List_BAP_Gen2-Night_Vision_0x18,not activated
- (48)-Car_Function_List_BAP_Gen2-Night_Vision_0x18_msg_bus,CAB_9
- (49)-Car_Function_List_BAP_Gen2-LDW_HCA_0x19,activated
- (50)-Car_Function_List_BAP_Gen2-LDW_HCA_0x19_msg_bus,Comfort data bus
- (51)-Car_Function_List_BAP_Gen2-SWA_0x1A,not activated
- (52)-Car_Function_List_BAP_Gen2-SWA_0x1A_msg_bus,Comfort data bus
- (53)-Car_Function_List_BAP_Gen2-AWV_0x1B,activated
- (54)-Car_Function_List_BAP_Gen2-AWV_0x1B_msg_bus,Terminal 15
- (55)-Car_Function_List_BAP_Gen2-Hybrid_0x1D,not activated
- (56)-Car_Function_List_BAP_Gen2-Hybrid_0x1D_msg_bus,Databus drivetrain
- (57)-Car_Function_List_BAP_Gen2-SideView_0x1E,not activated
- (58)-Car_Function_List_BAP_Gen2-SideView_0x1E_msg_bus,CAB_9
- (59)-Car_Function_List_BAP_Gen2-Reversible_Seat_Belt_Tightener_0x1F,not activated
- (60)-Car_Function_List_BAP_Gen2-Reversible_Seat_Belt_Tightener_0x1F_msg_bus,Comfort data bus
- (61)-Car_Function_List_BAP_Gen2-Passanger_Seat_0x20,not activated
- (62)-Car_Function_List_BAP_Gen2-Passanger_Seat_0x20_msg_bus,Comfort data bus
- (63)-Car_Function_List_BAP_Gen2-traffic_sign_recognition_0x21,not activated
- (64)-Car_Function_List_BAP_Gen2-traffic_sign_recognition_0x21_msg_bus,Comfort data bus
- (65)-Car_Function_List_BAP_Gen2-weariness_rcognition_0x22,not activated
- (66)-Car_Function_List_BAP_Gen2-weariness_rcognition_0x22_msg_bus,Comfort data bus
- (67)-Car_Function_List_BAP_Gen2-BCmE_0x23,not activated
- (68)-Car_Function_List_BAP_Gen2-BCmE_0x23_msg_bus,Comfort data bus
- (69)-Car_Function_List_BAP_Gen2-Angle_Of_Slope_0x24,not activated
- (70)-Car_Function_List_BAP_Gen2-Angle_Of_Slope_0x24_msg_bus,Comfort data bus
- (71)-Car_Function_List_BAP_Gen2-Battery_Management_0x25,not activated
- (72)-Car_Function_List_BAP_Gen2-Battery_Management_0x25_msg_bus,Comfort data bus
- (73)-Car_Function_List_BAP_Gen2-Brake_0x26,not activated
- (74)-Car_Function_List_BAP_Gen2-Brake_0x26_msg_bus,Comfort data bus
- (75)-Car_Function_List_BAP_Gen2-Start_Stop_reasons_0x27,not activated
- (76)-Car_Function_List_BAP_Gen2-Start_Stop_reasons_0x27_msg_bus,Comfort data bus
- (77)-Car_Function_List_BAP_Gen2-TV_tuner_0x2C,not activated
- (78)-Car_Function_List_BAP_Gen2-TV_tuner_0x2C_msg_bus,Comfort data bus
- (79)-Car_Function_List_BAP_Gen2-Amplifier_0x2D,not activated
- (80)-Car_Function_List_BAP_Gen2-Amplifier_0x2D_msg_bus,Comfort data bus
- (81)-Car_Function_List_BAP_Gen2-RearSeatEntertainment_0x2E,not activated
- (82)-Car_Function_List_BAP_Gen2-RearSeatEntertainment_0x2E_msg_bus,Comfort data bus
- (83)-Car_Function_List_BAP_Gen2-Ecall_0x33,not activated
- (84)-Car_Function_List_BAP_Gen2-eCall_0x33_msg_bus,Comfort data bus
- (85)-Car_Function_List_BAP_Gen2-MFL_Jocker_0x34,not activated
- (86)-Car_Function_List_BAP_Gen2-MFL_Jocker_msg_bus_0x34,Comfort data bus
- (87)-Car_Function_List_BAP_Gen2-Special_Functions_0x35,not activated
- (88)-Car_Function_List_BAP_Gen2-Special_Functions_msg_bus_0x35,Comfort data bus
- (89)-Car_Function_List_BAP_Gen2-Trailer_Assistant_0x36,not activated
- (90)-Car_Function_List_BAP_Gen2-Trailer_Assistant_msg_bus_0x36,Comfort data bus

adpmap-5f-850-035-049_MIB2

- (91)-Car_Function_List_BAP_Gen2-ENI_0x37,not activated
- (92)-Car_Function_List_BAP_Gen2-ENI_0x37_msg_bus,Comfort data bus
- (93)-Car_Function_List_BAP_Gen2-Range_Data_0x39,not activated
- (94)-Car_Function_List_BAP_Gen2-Range_Data_msg_bus_0x39,Comfort data bus
- (95)-Car_Function_List_BAP_Gen2-Pedestrian_Assist_0x3A,not activated
- (96)-Car_Function_List_BAP_Gen2-Pedestrian_Assist_msg_bus_0x3A,Comfort data bus
- (97)-Car_Function_List_BAP_Gen2-Seat_Pneumatic_0x3B,not activated
- (98)-Car_Function_List_BAP_Gen2-Seat_Pneumatic_msg_bus_0x3B,Comfort data bus
- (99)-Car_Function_List_BAP_Gen2-efficiency_assist_0x3C,not activated
- (100)-Car_Function_List_BAP_Gen2-efficiency_assis_msg_bus_0x3C,Comfort data bus
- (1)-Car_Function_List_CAN_Gen2-MFL,Available
- (2)-Car_Function_List_CAN_Gen2-MFL_msg_bus,Databus Infotainment
- (3)-Car_Function_List_CAN_Gen2-Oil_level,Not available
- (4)-Car_Function_List_CAN_Gen2-Oil_level_msg_bus,Databus drivetrain
- (5)-Car_Function_List_CAN_Gen2-PDC_audio_lowering,Available
- (6)-Car_Function_List_CAN_Gen2-PDC_audio_lowering_msg_bus,Suspension data bus
- (7)-Car_Function_List_CAN_Gen2-VIN,Available
- (8)-Car_Function_List_CAN_Gen2-VIN_msg_bus,Comfort data bus
- (9)-Car_Function_List_CAN_Gen2-Driving_school,Not available
- (10)-Car_Function_List_CAN_Gen2-Driving_school_msg_bus,Databus Infotainment
- (11)-Car_Function_List_CAN_Gen2-Adaptive_key,Not available
- (12)-Car_Function_List_CAN_Gen2-Adaptive_key_msg_bus,Comfort data bus
- (1)-Dashboard_Display_Configuration-navigation_map_transmission_mode,OFF
- (2)-Dashboard_Display_Configuration-navigation_map_compression_mode,H264
- (3)-Dashboard_Display_Configuration-navigation_map_resolution,resolution_1
- (4)-Dashboard_Display_Configuration-crossroad_detail_map_transmission_mode,OFF
- (5)-Dashboard_Display_Configuration-crossroad_detail_map_compression_mode,RLE
- (6)-Dashboard_Display_Configuration-crossroad_detail_map_resolution,resolution_1
- (7)-Dashboard_Display_Configuration-coverart,On
- (8)-Dashboard_Display_Configuration-stationart,OFF
- (9)-Dashboard_Display_Configuration-call_picture,On
- (10)-Dashboard_Display_Configuration-fastlist_most,OFF
- (1)-Dimming_Ambient_Illumination_Information_Control_Unit-X1,0
- (2)-Dimming_Ambient_Illumination_Information_Control_Unit-Y1,0
- (3)-Dimming_Ambient_Illumination_Information_Control_Unit-X2,50
- (4)-Dimming_Ambient_Illumination_Information_Control_Unit-Y2,50
- (5)-Dimming_Ambient_Illumination_Information_Control_Unit-X3,100
- (6)-Dimming_Ambient_Illumination_Information_Control_Unit-Y3,100
- (1)-Dimming_Ambient_Illumination_Operating_and_Display_Unit-X1,0
- (2)-Dimming_Ambient_Illumination_Operating_and_Display_Unit-Y1,0
- (3)-Dimming_Ambient_Illumination_Operating_and_Display_Unit-X2,50
- (4)-Dimming_Ambient_Illumination_Operating_and_Display_Unit-Y2,50
- (5)-Dimming_Ambient_Illumination_Operating_and_Display_Unit-X3,100
- (6)-Dimming_Ambient_Illumination_Operating_and_Display_Unit-Y3,100
- (1)-Dimming_Illumination_for_Display_Unit-X1,0
- (2)-Dimming_Illumination_for_Display_Unit-Y1,1 %
- (3)-Dimming_Illumination_for_Display_Unit-X2,10
- (4)-Dimming_Illumination_for_Display_Unit-Y2,1 %
- (5)-Dimming_Illumination_for_Display_Unit-X3,100
- (6)-Dimming_Illumination_for_Display_Unit-Y3,8 %
- (7)-Dimming_Illumination_for_Display_Unit-X4,150

adpmap-5f-8S0-035-049_MIB2

(8)-Dimming_Illumination_for_Display_Unit-Y4,20 %

(9)-Dimming_Illumination_for_Display_Unit-X5,220

(10)-Dimming_Illumination_for_Display_Unit-Y5,60 %

(11)-Dimming_Illumination_for_Display_Unit-X6,253

(12)-Dimming_Illumination_for_Display_Unit-Y6,100 %

Operating_and_Display_Unit_1_Proximity_Sensor_Basic_Adaptation,04 01 52 04 52 10
52 40 52 32 00 64 00 C8 00 AE 01 96 00 C8 00 14 00 14 00 14 00 14 00 FF FF 00 00
00 00 00 00 00 00 55

p_damping_Display,5 ms

p_HMI_Display,13 %

(1)-Radio_Level_Quality_Offsets-Set_AM_Quality_Level_Offset,0

(2)-Radio_Level_Quality_Offsets-Set_FM_Quality_Level_Offset,0

Startup_Screen_Sticker_HMI,00 02

(1)-Testmode_Video_speed_cutoff-speed_limit,0 km/h

(2)-Testmode_Video_speed_cutoff-PIN,0